

CRITICAL INSTRUCTIONS

Application: **Fiat Ducato**

Part Number:

796122-5001S/ 796122-5005S

806850-5001S/806850-5002S/

806850-5003S

WHEN FITTING THIS TURBO, IT IS **CRITICAL** THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

- **Potential Actuator Damage to Fiat Ducato turbochargers**

We are aware of issues that may affect these vehicles and lead to premature turbocharger replacement.

Water ingress to the actuator and/or its position sensor may damage the internal components and prevent the actuator controlling the turbocharger, leading to Diagnostic Trouble Codes or Error Codes, and potentially reduced power mode.

Owners should ensure they implement all Fiat Service Bulletins relating to water ingress:

1. **Engine compartment water ingress** via the windscreen drain channel. Modifications may be required to prevent water collecting on top of the engine and damaging the turbo and other components.
2. **Water ingress to the turbocharger actuator control valve** (PWM valve or Elettrovalvola). Make sure water cannot enter the control system; it may damage the actuator and prevent it controlling the turbocharger.

If you have any questions about this issue, ask the supplier of this unit before starting work. All necessary vehicle modifications should be completed before replacing a turbocharger.

Important: warranty does not cover damage caused by water ingress to the Actuator and/or Linear Position Sensor.

Any questions regarding the above should be directed to the supplier of this unit before commencing any work

