

CRITICAL INSTRUCTIONS

Part Number:

Various

Application: **BMW (All BMW Diesel Engines) / Land Rover**

WHEN FITTING THIS TURBO, IT IS **CRITICAL** THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

- **Replace Engine Breather Filter, BMW Diesel Engines**

A new breather filter should be fitted at the same time as the turbocharger

The engine breather system on BMW diesel engines has a tendency to become restricted over time, causing an increase in sump pressure. The increased oil pressure inside the turbocharger causes oil to pass into the exhaust and air intake systems, resulting in blue engine smoke. This may occur after a new turbocharger has been fitted, even if the vehicle wasn't previously displaying this problem. Replacing the filter resolves this issue.

Any questions regarding the above should be directed to the supplier of this unit before commencing any work

